

ANNOTATED SHEET I
 (Changed indicated in Red)

100(0)	$Y_0 Cr_0 Cb_0$	Y_1	$Y_2 Cr_1 Cb_1$	Y_3	$Y_4 Cr_2 Cb_2$	Y_5	\dots	$Y_{x-1} Cr_{(x-1)} Cb_{(x-1)}$	\dots	Y_x
100(1)	$Y_0 Cr_0 Cb_0$	Y_1	$Y_2 Cr_1 Cb_1$	Y_3	$Y_4 Cr_2 Cb_2$	Y_5	\dots	$Y_{x-1} Cr_{(x-1)} Cb_{(x-1)}$	\dots	Y_x
100(2)	$Y_0 Cr_0 Cb_0$	Y_1	$Y_2 Cr_1 Cb_1$	Y_3	$Y_4 Cr_2 Cb_2$	Y_5	\dots	$Y_{x-1} Cr_{(x-1)} Cb_{(x-1)}$	\dots	Y_x
100(3)	$Y_0 Cr_0 Cb_0$	Y_1	$Y_2 Cr_1 Cb_1$	Y_3	$Y_4 Cr_2 Cb_2$	Y_5	\dots	$Y_{x-1} Cr_{(x-1)} Cb_{(x-1)}$	\dots	Y_x
\vdots										
100(N)	$Y_0 Cr_0 Cb_0$	Y_1	$Y_2 Cr_1 Cb_1$	Y_3	$Y_4 Cr_2 Cb_2$	Y_5	\dots	$Y_{x-1} Cr_{(x-1)} Cb_{(x-1)}$	\dots	Y_x

FIGURE 2

48Y(0)	$Y_0, Y_1, Y_2, \dots, Y_{15}$
48Y(1)	$Y_{16}, Y_{17}, Y_{18}, \dots, Y_{31}$
\vdots	
48Y(i)	$Y_{16i}, Y_{16i+1}, Y_{16i+2}, \dots, Y_{16i+15}$
\vdots	

48Y

48C(0)	$C_0, C_1, C_2, \dots, C_{15}$
48C(1)	$C_0, C_1, C_2, \dots, C_{15}$
\vdots	
48C(i)	$C_{8i}, C_{8i+1}, C_{8i+2}, \dots, C_{8i+7}$
\vdots	

48C

FIGURE

3A

ANNOTATED SHEET
 (Changed indicated in Red)




FIGURE 10